

ASSEMBLY INSTRUCTION

H08F-HK-US3012LR


Ax2



Bx2




Cx2




Dx2




Ex1




Fx1



1










Wait 72 hours for rebound


2







3






4





5

x2



6

